

Certificate according to EN ISO 3834-2



We confirm that the company

GENERAL SOLUTIONS SLN DOO

Temišvarski Drum bb, 23000 Zrenjanin, SRBIJA

Unit: GENERAL SOLUTIONS SLN DOO

Located in: Temišvarski Drum bb, 23000 Zrenjanin, SRBIJA

has proved its ability to fulfill the quality requirements for fusion welding of metallic materials, covered by the ranges described in standard

SISTEN ISO 3834-2:2006

First issue date: 27. 12. 2018

Date of expiry: 27. 12. 2020

Remarks: This certificate remains valid as long as the conditions laid down in the technical specification in reference or the manufacturing conditions in the factory itself are not modified significantly.
The current validity of the certificate can be checked on: info@i-var.si

To this certificate belongs the appendix.

Place and issue date: Ljubljana, 27. 12. 2019



Dr.-Ing. Miro Uran, General Manager





Certificate according to EN ISO 3834-2

Appendix

Extent of validity of Certificate No. 2042-3834-312I-19

Product Standard(s):

EN 1090-2

Alternative Standard(s) (refer to ISO 3834-5):

EN ISO 9606-1, EN ISO 14731, EN ISO 9712,
EN ISO 15614-1, EN ISO 15609-1, EN ISO 17635, EN ISO 17637

Welding processes (ISO 4063)

135
136

Parent material groups (ISO/TR 15608)

1.1
1.1

Welding Coordination Personnel:

Name	Qualification	Job function and level*
Dalibor Grujić	IWE	Welding coordinator – comprehensive

* The level must be stated in order to comply with ISO 14731.

Dr.-Ing. Miro Uran, univ.dipl.inž.

General Manager



INSTITUT ZA VARILSTVO
Welding Institute